



**OFFICE OF THE ASSISTANT EXECUTIVE ENGINEER
DHARAMGARH (R&B) SUB-DIVISION, DHARAMGARH**

Letter No: 268-----/

Date: 19/07/2021-----/

To,

**The Principal,
Kendriya Vidyalaya Dharamgarh,
Vocational Collage Campus,
Kalahandi (Odisha) Pin-766015.**

Sub :- Structural safety certificate of Kendriya Vidyalaya Dharamgarh, Vocational Collage Campus, Kalahandi (Odisha) Pin-766015.

Ref;- Your letter No.F.320112/KVDGH/2021-22/31 Dated 17.07.2021.

Sir,

With reference to the subject cited above, it is to state that after due inspection, it is found that all Buildings of **Kendriya Vidyalaya Dharamgarh, Vocational Collage Campus, Kalahandi (Odisha) Pin-766015** meant for class rooms, office, library etc. are structurally safe for the purpose under normal weather condition for the year – 2021-22.

Yours faithfully,

Asst.Executive Engineer,
Dharamgarh, (R&B) Sub –Division

Memo No: -----/

Date: -----/

Copy submitted to the Executive Engineer, Kalahandi (R&B) Division, Bhawanipatana for information.

Asst.Executive Engineer,
Dharamgarh, (R&B) Sub –Division